



## MAIN ADAPTER SGX 220-12V 60W

In compact Noryl casing (recommended for transformers). With superior capacity of 5,0 A at 16 Volt no load and 12 Volt under load = 60 VA (DC). Master switch for turning off transformer without needing to unplug.

Red LED indicates "ready".

PTC protection against overload (plugged in machine will not restart automatically). After cooling down, the mains plug should briefly be unplugged to reset the adapter. Practical design with storage holes for bits with 2,35 mm and 3 mm shafts. Foldable tool rest - keeps the tool being used safely on standby.

Capacity: 5,0 A at 16 Volt no load and 12 Volt under load = 60 VA (DC). Primary supply 220/240 Volt. Thyristor electronic speed control (with feedback) for optimum tool speed and high torque at low speeds. 3 polarised sockets, and 1 pair of sockets for standard plugs (4 mm diameter).

SKU 11127